

OVERALL ASSESSMENT

2026 Toyota Corolla Altis

● Needs Attention



SCAN TO VERIFY



FRONT



BACK

INSPECTION REFERENCE / REPORT ID

TXI-2026-000004

INSPECTION DATE

11 August 2026

CUSTOMER / DEALER NAME

Masab Bin Zia

VEHICLE INFORMATION & INSPECTION DETAILS

VEHICLE MAKE

Toyota

VEHICLE MODEL

Corolla

VARIANT / TRIM

Altis

EXTERIOR COLOR

White

MODEL YEAR

2026

ENGINE CAPACITY

1.6

BODY TYPE

☒ SEDAN ☐ HATCHBACK ☐ SUV ☐ PICKUP ☐ OTHER

ENGINE NUMBER

DEV-ENGINE-001

CHASSIS / VIN NUMBER

DEV-CHASSIS-001

ODOMETER READING

50000 KM

REGISTRATION NUMBER

LES-DEMO-001

REGISTRATION STATUS

☒ REGISTERED ☐ UNREGISTERED

REGISTRATION CITY / PROVINCE

Karachi, Sindh

CUSTOMER PHONE

03182828830

INSPECTION CATEGORY

Sedan

BRANCH

PECHS Main Branch

INSPECTION TEAM

Farooq Ahmed, Jamil (Mechanic), Farooq (Painter), Maaz (Helper), Nadir (Electrician)

CONDITION RATING GUIDE

● GOOD — No Issue Observed

● ATTENTION — Minor issue / maintenance advised

● MAJOR — Major issue / repair history / critical observation

EXECUTIVE SUMMARY (CUSTOMER OVERVIEW)

CATEGORY				REMARK
Structural / Body Frame	☒	☐	☐	OK
Engine & Transmission	☐	☒	☐	Oil level slightly low
Suspension & Steering	☒	☐	☐	OK
Braking System	☒	☐	☐	OK
Electrical & Electronics	☒	☐	☐	OK
Interior & Exterior	☒	☐	☐	OK
Tyres & Wheels	☒	☐	☐	OK
Road Test Result	☒	☐	☐	OK

COMMENTS

The vehicle presents in excellent condition, consistent with a brand-new unit. The odometer reading of 50,000 kilometers is supported by the vehicle's overall presentation and performance during the assessment.


The vehicle successfully completed a 226-point roll test, confirming that all inspected systems and mechanical components are functioning as intended. Based on this comprehensive evaluation, the vehicle demonstrates a high level of operational integrity and appears to have been well-maintained.

01 STRUCTURAL / BODY FRAME INSPECTION

CATEGORY				REMARK	PHOTO
Radiator Core Support	☒	☐	☐	OK	
Left Strut Tower Apron	☒	☐	☐	OK	
Right Strut Tower Apron	☒	☐	☐	OK	
Front Chassis Rails (L/R)	☒	☐	☐	OK	
Firewall / Cowl Panel	☒	☐	☐	OK	
A Pillars (L/R)	☒	☐	☐	OK	
B Pillars (L/R)	☒	☐	☐	OK	
C Pillars (L/R)	☒	☐	☐	OK	

CATEGORY				REMARK	PHOTO
Boot Floor	☒	☐	☐	OK	
Rear Lock Panel	☒	☐	☐	OK	
Front Subframe	☒	☐	☐	OK	
Rear Subframe	☒	☐	☐	OK	

02 ENGINE / TRANSMISSION / POWERTRAIN

CATEGORY				REMARK	PHOTO
Engine Oil Level	☐	☒	☐	Oil level slightly low	
Engine Oil Leakage	☒	☐	☐	OK	
Transmission Leakage	☒	☐	☐	OK	
Brake Fluid	☒	☐	☐	OK	
Coolant Leakage	☒	☐	☐	OK	
Washer System	☒	☐	☐	OK	
Engine Noise	☒	☐	☐	OK	
Engine Vibration	☒	☐	☐	OK	
Engine Blow By	☒	☐	☐	OK	
Belts Condition	☒	☐	☐	OK	
Wiring Harness	☒	☐	☐	OK	
Engine Mounts	☒	☐	☐	OK	
Transmission Mounts	☒	☐	☐	OK	
Hoses & Pulleys	☒	☐	☐	OK	

CATEGORY				REMARK	PHOTO
Catalytic Converter	☒	☐	☐	OK	
Exhaust System	☒	☐	☐	OK	
Radiator Condition	☒	☐	☐	OK	
Cooling Fan	☒	☐	☐	OK	

03 BRAKING SYSTEM

CATEGORY				REMARK	PHOTO
Front Brake Discs	☒	☐	☐	OK	
Front Brake Pads	☒	☐	☐	OK	
Parking / Hand Brake	☒	☐	☐	OK	

04 SUSPENSION & STEERING

CATEGORY				REMARK	PHOTO
Ball Joints	☒	☐	☐	OK	
Tie Rod Ends	☒	☐	☐	OK	
Rack Ends	☒	☐	☐	OK	
Bushes / Links	☒	☐	☐	OK	
Front Shocks	☒	☐	☐	OK	
Rear Shocks	☒	☐	☐	OK	
Steering Operation	☒	☐	☐	OK	
Wheel Alignment	☒	☐	☐	OK	

05 AIR CONDITIONING / HEATER

CATEGORY				REMARK	PHOTO
AC System	☒	☐	☐	OK	
Cooling Performance	☒	☐	☐	OK	
Heating Performance	☒	☐	☐	OK	
Blower Operation	☒	☐	☐	OK	
Compressor	☒	☐	☐	OK	

06 ELECTRICAL & ELECTRONICS

CATEGORY				REMARK	PHOTO
Battery Condition	☒	☐	☐	OK	
Charging System	☒	☐	☐	OK	
Alternator	☒	☐	☐	OK	
Instrument Cluster	☒	☐	☐	OK	

07 INTERIOR CONDITION

CATEGORY				REMARK	PHOTO
Steering Wheel	☒	☐	☐	OK	
Seats Upholstery	☒	☐	☐	OK	
Dashboard	☒	☐	☐	OK	
Roof Lining	☒	☐	☐	OK	

08 EXTERIOR & LIGHTING

CATEGORY				REMARK	PHOTO
Windshields	☒	☐	☐	OK	

CATEGORY				REMARK	PHOTO
Headlights	☒	☐	☐	OK	NO IMAGE
Wipers	☒	☐	☐	OK	NO IMAGE

09 TYRES & WHEELS


CATEGORY				REMARK	PHOTO
Tyre Brand / Manufacturer	☒	☐	☐	OK	NO IMAGE
Tyre Manufacturing Date	☒	☐	☐	OK	NO IMAGE
Uneven Wear Pattern	☒	☐	☐	OK	NO IMAGE
Sidewall Condition	☒	☐	☐	OK	NO IMAGE
Tyres Matching	☒	☐	☐	OK	NO IMAGE
Wheel Condition	☒	☐	☐	OK	NO IMAGE

10 ROAD TEST OBSERVATION

ITEM				REMARK	PHOTO
Engine Performance	☒	☐	☐	OK	NO IMAGE
Gear Shifting	☒	☐	☐	OK	NO IMAGE
Brake Response	☒	☐	☐	OK	NO IMAGE
Suspension Noise	☒	☐	☐	OK	NO IMAGE
Steering Feel	☒	☐	☐	OK	NO IMAGE

EXTERIOR CONDITION MAP

A1	Scratch — Minor paint scratch on the surface
U1	Dent — Minor dent on the panel
DS	Dent with Scratch — Dent with visible paint damage
D	Dimples — Multiple minor dents across the panel
P	Repainted Panel — Panel shows signs of repaint work
R	Repair Work — Evidence of previous repair present
W	Normal Wear & Tear — Minor marks consistent with regular use



EXTERIOR DEFECT PHOTOS

CODE	DETAIL	PHOTO
W — Scratch — Minor paint scratch on the surface	—	

DISCLAIMER

This Vehicle Condition Inspection Report is based on a visual and functional assessment carried out at the time of inspection using non-invasive methods. Findings reflect the vehicle's condition as observed on the inspection date and may change with further use, maintenance, or repair. This report does not constitute a warranty, guarantee, or certification of future performance, and latent defects not detectable through standard visual/functional checks may exist. Tweak X Inspect and its inspectors accept no liability for decisions made solely on the basis of this report.